



Photo 1 – View of N19710 windscreen damage



Photo 2 – View of right aileron damage of N1308U




Photo 3 – Diagram of ramp and taxiway showing an illustration of event