




**Photo 1 – Detached Engine #2 (Right Side) Exhaust Duct (Photo Courtesy of FAA)**



**Photo 2 – Heat Damage to the Upper Skin of the Engine Compartment. (Photo Courtesy of FAA)**