



Photo 1 – View of the ground winch system (courtesy of the flight instructor).



Photo 2 – View of the broken weak link/safety link (courtesy of the flight instructor).



Photo 3 – View of the substantial damage sustained to the fuselage (courtesy of the flight instructor).



Photo 4 – View of the substantial damage sustained to the fuselage and both wings (courtesy of the flight instructor).



Photo 5 – View of the substantial damage sustained to the right wing (courtesy of the flight instructor).