



**Photo 1 – View of damage to the inboard, right side horizontal stabilizer and empennage (Courtesy of Pilot)**



**Photo 2 – View of damage to the inboard, right side horizontal stabilizer, and empennage (Courtesy of Pilot)**



**Photo 3 – View of post-accident left fuel tank quantity (Courtesy of Pilot)**



**Photo 4 – View of post-accident right fuel tank quantity (Courtesy of Pilot)**