

Photo 1 – View of damage to tail bulkhead and aft stringers (Courtesy of FAA)



Photo 2- View of damage to the aft fuselage (Courtesy of FAA)