



**Photo 1 – Right wing leading edge**



**Photo 2 – Right wing internal damage**