



Photo 1 – View of the inverted airplane with damage to the right wing lift strut and empennage (Courtesy of FAA)



Photo 2 – View of the inverted airplane with damage to the empennage (Courtesy of FAA)