



Photo 1 – Separated Tail Rotor Drive Shaft (Photo Courtesy of Pilot)