



Photo 1 – N431SS, at the accident site, showing damage to the right wing. Photo courtesy of the pilot.



Photo 2 – Left view, showing damage to the left wing. Photo courtesy of the pilot.



Photo 3 – Right view showing damage to the right wing, vertical stabilizer, and the rudder. Photo courtesy of the pilot.