

CEN23LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front right side view of airplane at accident site (NTSB Photo)



Photograph 2 - Rear right side view of airplane at accident site (NTSB Photo)



Photograph 3 - Front view of airplane at accident site (NTSB Photo)



Photograph 4 - Airplane engine during examination (NTSB Photo)



Photograph 5 - Airplane instrument panel during examination (NTSB Photo)



Photograph 6 - Airplane prior to the accident (Courtesy of previous owner, Larry Moore)