

While making S/B approach at McI Price Lock  
Current set stern end of tow to wall and landed  
tow 2nd coupling back from head land on end of  
long wall. Wind blowing toward wall also. Draft  
to wall caught 9 Lds on stern and set harder  
than 6 mts on head. Which caused tow to go  
to wall stern first.

Jackie Henshaw 3-19-2021

[REDACTED] [REDACTED]  
V [REDACTED]

03/19/21

Charles Brocato - Mate - ~~Mr Kevin McKeed~~

Was on Head of tow Coming down on  
Met-Price lock and dam. pilot told to  
Watch out stern of tow coming before head  
came in and Saddled bag tow on end of  
cong wall.

3/19/21 Charles Brocato  
Mate [REDACTED] [REDACTED]

03/19/2021

We was out on the head getting ready to go through the lock. The Pilot said we was saddlebagging and there was a load boom. The 2 barges we was on broke loose from the rest and we started floating off to the port side. We was try to fire off somewhere to we wouldn't continue to float down into the channel. We tied off to the first thing we could to stop floating down stream. Then we wait tell for some one to come get us.

J H H H  
[REDACTED]

Jacob Hahn