



*Figure 1. Hawthorne Street after water main damaged. CAT 305 E2 excavator on right with jackhammer attachment. View facing southwest. Photograph courtesy of Kilford Engineering, Inc.*





*Figure 2. Hawthorne Street after water main damaged. CAT 305 E2 excavator on right with jackhammer attachment. View facing northwest. Photograph courtesy of Kilford Engineering, Inc.*





Figure 3. Damaged water main on Hawthorne Street. Photograph courtesy of Kilford Engineering, Inc.





Figure 4. Hawthorne Street prior to excavation work, showing one-call markings and evidence of saw-cutting. Photograph courtesy of Kilford Engineering, Inc.