


# *Proassist III*

Starboard side deckhouse weathertight door



Photographs are screen shots from underwater video taken on  
January 2, 2021.





Securing rod  
(disconnected from top of  
door)


Weathertight door

*Proassist III* starboard side





*Proassist III* starboard weathertight door



*Proassist III* starboard weathertight door