2009 AIRCRAFT MAINTENANCE MAINTENANCE RECORDKEEPING SYSTEM

PROPELLER MAINTENANCE RECORDS





PROPELLER MAINTENANCE RECORDS

	Log No. 2	litions Air
Aircraft Registration No. N5240C	-	
Propeller Manufacturer Amt zell		
Hub Model HC-DaMVa0-7	_	G35, 35R
Blade Design No.		,
Hub Serial No. AVA348	_	
		with ell
Blade Serial No's. 1. J30/3/	_	2, . D-220
2. T30/27	_	
3		
4		
Pitch Range:		
Low		
eather Reverse		
Governor Manufacturer		e Page
Madel No		fthe
Serial No.		
Date installed on aircraftH	lours	81
Time Between Overhaus		e 2)
If used on multi-engine aircraft:		
☐ Right ☐ Left		1
☐ Front ☐ Rear		Branc



(All applicable information must be filled in)

PO BOX 1359 / SOUTHOLD, NY 11971-0965 (516) 765-9375 FAX: (516) 765-9359

© 1979 AeroTech Publications Inc.

, or both. 'AR 21.47

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
3-23-13	5070.0			Z CRATILLY THIS PIPELLER HAS
				BREW INSPECTED EPOLO AN PAPUAL
				ENSPECTION AND FOUND TO BE IN AN
				ASKWORTHY CONCERON.
				A
9-21-13	51027			REMOERD PROPEUTER & INSTALLED MEN
				SPENNER I BUCKITEAD, C/WAD
				2013-15-04 BY REPLACEMENT OF
				PROPRECIAL CONTROL DEAPHRACEN TOTAL
				PARA (P) OF AD.
6-7-19	9119.7			I CELTAFY THAT THES PROPECLED 1405
				BEEN ZWSPECTED EVALUE AR LYNNIGE
				INSPECTION AND FOUND TO BE IN
				AN ATREORITHY CONFITION.
0416	5135.2	0		I CENTILY THAT THIS PROP. 1425 BEEN
				ENSPECTED FLAN AN AUMAL INSR AND
				FOUR TO BE IN AN ATKWORTHY CONDITION.
2= 50/	5/36-0			T DIDESTE THAT THE DIDECTED IND ACCOUNT
-27-18	7/3020			I CHOSELY THAT THIS PROPECTED HAS BEEN
	-			INSPECTED TOOK OF HAVUEL ENGRETTON
				MD POUND TO BE IN DE ANCHORDERY COMMITTEN
				SUB-TOTALS this page
				TOTALS—Carry forward to next page

2)

ch, 210 oth.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WOR
	SERVICE	- Comment		TOTALS brought forward from previous page
-	PONSON A	AIR CRAFT	& MARINE S	SERVICES, INC. N5240C
- 6	KONSON	inclui i c	z mindre i	B-35
. Н	OUSTON, 7	TX 77075		S/N D-2631
				Propeller PTSN 662.3 6/0 -
	lodel HC-D2	MV20-7		Propeller PTSN 662.3 495.4 ACTT: 5158.6
	N AVA348	sensation ass	nnloted IAW	
wi	th Aeroshell	6 Serviced	A-36 Huh Re	FAR 43 Appendix (D) and Hartzell MM 140. Serviced Blades earing with GADUS S2 V100 2 grease. Replaced A-36 Hub
Be	earing and Pi	ston Housing	P/N C-12-2	Replaced Bladder Diaphragm P/N B-119-2. Replace in 24 Mo or
25	0 Hrs. Comp	lied with AL	65-21-04.	The place in 24 Mio or
I ce	ertify this pro	opeller has be	een inspected	IAW an Annual/100 HR Inspection and found to be in Airworthy
con	dition this ti	me and date	and return to	service.
			·	1
Sion	n: Craig P. A	roncon		
Sign	i. Claig I . A	Tollson A	(Date: 10/09/2019
-1.				
				-
ARC	NSON AIR	CRAFT & M	IARINE SEF	RVICES, INC. N5240C
ARC	NSON AIR	CRAFT & M	IARINE SEF	B-35
	ONSON AIR		MARINE SEF	B-35 S/N D-2631
нос	310N, 1X	17075	IARINE SEF	B-35 S/N D-2631 ACTT: 5183,5
Mode	el HC-D2MV	17075	IARINE SEF	B-35 S/N D-2631
Mode S/N A Remo	el HC-D2MV AVA348 oved propello	77075 720-7 er, resecured	spinner hub	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3
Mode S/N A Remo	el HC-D2MV AVA348 oved propello	77075 720-7 er, resecured	spinner hub	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3
Mode S/N A Remo	el HC-D2MV AVA348 oved propello	77075 720-7 er, resecured	spinner hub	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3
Mode S/N A Remo	el HC-D2MV AVA348 oved propello Aeroshell 6.	7/0/3 /20-7 er, resecured Serviced A-2	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease.
Mode S/N A Remo	el HC-D2MV AVA348 oved propello Aeroshell 6.	7/0/3 /20-7 er, resecured Serviced A-2	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3
Mode S/N A Remo	el HC-D2MV AVA348 oved propello Aeroshell 6.	7/0/3 /20-7 er, resecured Serviced A-2	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease.
Mode S/N A Remo	el HC-D2MV AVA348 oved propello Aeroshell 6.	7/0/3 /20-7 er, resecured Serviced A-2	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease.
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propello Aeroshell 6.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease.
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to
Mode S/N A Remo with A	el HC-D2MV AVA348 oved propelle Aeroshell 6. fy this prope e.	77073 720-7 er, resecured Serviced A-3 eller has been	spinner hub 36 Hub Beari	B-35 S/N D-2631 ACTT: 5183,5 PTTSN:519.3 and replaced propeller as per Hartzell MM Serviced Blades ing with GADUS S2 V100 2 grease. and found to be in Airworthy condition this date and return to

	SERVIO	CE SINCE OVERHAUL	TIME	S	DESCRIPTION OF WORK IGNATURE & CERTIFICATE NO. OF F				
				TOTALS br	ought forward from previous pag	ge			
		Tex	cas Aircra CR	ft Prope	ller & Accessories DR559C				
		PROP	ELLER DYN	AMIC BAL	ANCE				
		_ AC_	N52	40C					
		Syste	System: Chadwick Vibrex 2000 · S/N: 1041						
		Start	Starting IPS						
		Endir	ng IPS	.01	200				
		-	nician:		-				
					100 - 100 -				
		. Signa	ture:	7	Date: 2/8/21				
					the control of the same of the	Å			
	- Au	roving Civil Aviation uthority / Country: JNITED STATES			LEASE CERTIFICATE WORTHINESS APPROVAL TAG	3 Form Tracking Number:			
		tion Name and Address:	TEXAS AIRCRAF 1711 CR 130 - Pe		ELLER & ACCESS 7RDR559C	5. Work Order/Contract/ Invoice Number: 19130			
- 1	6. 7. Description:				antity: Serial ** Taber				
	Item:	Description:		Qua	ntity: Serial 1" nher	Status / Work			
	Item:	Propeller	HC-D2MV2		nity: Serial 1 aber 1 A. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Status / Work: REPAIRED			
	1 12. Remarks: Disassemb Blade Mod	Propeller	HC-D2MV2	0-7	1 AN 4348				
	12. Remarks: Disassemb Blade Mod Blade S/N:	Propeller oled, and Resealed tel#: MV8433N 130127, J30131	HC-D2MV2	0-7 unual Nos: 100	1 AN 4348 E, 133C, 202A 14a. N 14 CFR 43.0 3 ctum to Service	REPAIRED			
	1 12. Remarks: Disassemb Blade Mod Blade S/N: Certifies the it	Propeller lled, and Resealed del#: MV8433N	HC-D2MV2	0-7 unual Nos: 100	1 AN 4348 E, 133C, 202A L4 CFR 43.7 Return to Service Other regulation specified in E Certifies that unless other are specified in bl 11 and described in Block 17 was accomplish Code of Federal Regulations, part 43 and in	REPAIRED Block 12 ock 12, the work identified in Block hed in scoordance with Title 14, respect to the work.			
	1 12. Remarks: Disassemb Blade Mod Blade S/N: Certifies the it	Propeller pled, and Resealed del#: MV8433N J30127, J30131 terms identified above were roved design data and an approved design data sp	HC-D2MV2	0-7 unual Nos: 100 formity to	1 AN 4348 E, 133C, 202A 14a.	REPAIRED Block 12 ock 12, the work identified in Block hed in scoordance with Title 14, respect to the work.			
	1 12. Remarks: Disassemb Blade Mod Blade S/N: Certifies the it Appr Non- 13b. Authorized	Propeller pled, and Resealed del#: MV8433N J30127, J30131 terms identified above were roved design data and an approved design data sp	HC-D2MV2i IAW Hartzell Ma re manufactured in con e in a condition for saft ecified in Block 12 13c. Appl. Aut	formity to correction.	1 AN 4348 E, 133C, 202A L4a. A 14 CFR 43.73 actum to Service Other regulation specified in El Certifies that unless other are a specified in B1 and described in Block 17 was accomptise. Code of Federal Regulations, part 43 and in the items are approved for return to service	REPAIRED Block 12 Block 12 Block 12 Block 12 Block 12 Block 14 Block 15 Block 16 Block 16 Block 16 Block 16 Block 17 Block 18 Bl			