



## **Survival Factors Photographs**

**Randolph, New Hampshire**

**HWY19MH010**

**(8 Pages)**



Photo 1 – Frontal left angle view of deformation to front of 2016 Ram 2500 pickup truck.



Photo 2 – Front left angle view of deformation and fire damage to front and right side of 2016 Ram 2500.





Photo 3 – Right side view of damage and deformation to 2016 Ram 2500.



Photo 4 – Right side angle view of 2015 Quality Trailers flatbed trailer.





Photo 5 – Interior view from outside right rear passenger window of postcrash fire damage to interior of 2016 Ram.



Photo 6 – Right side view of deformation to 1998 Harley Davidson Electric Glide FLHT.





Photo 7 – View of deformation to 2006 Harley Davidson Heritage Softail FLSTI.



Photo 8 – View of front-end deformation to 2012 Harley Davidson FLHTKCUSE7.





Photo 9 – View of damage to 2012 Harley Davidson Electra Glide Ultra Unlimited FLSTI.



Photo 10 – View of deformation to 2005 Harley Davidson Electra Glide Ultra Classic FLHTCUI.





Photo 11 – View of 2007 Harley Davidson Electra Glide Ultra Classic FLHTCU.



Photo 12 – View of damaged and burned 2012 Harley Davidson Electra Glide Ultra Limited FLHTK EL.





Photo 13 – View of minor damage to 2015 Harley Davidson Softail Deluxe FLST.



Photo 14 – View of minor damage to 2007 Harley Davidson CVO Road King FLHSE3.