



RECORD OF CONVERSATION

Tealeye Cornejo

Air Safety Investigator (Field)

Western Pacific Region

Date: 05/09/2022

Person Contacted: Art Granger, mechanic

Contact Information: [REDACTED]

NTSB Accident Number: WPR22LA128

Narrative:

According to Mr. Granger, he inspected the airplane and reported the following:

- Three of the engine mounts were broken during the accident sequence.
- Brakes functioned, but the left brake was spongy, a determination as to the origin of the sponginess was not identified.