

Surveillance Video Screenshots Hartford Airport

NTSB # ERA23LA121



Airplane on ramp, prior to engine start



Taxi commences



Airplane returned from runway to ramp after aborted takeoff. Completes a 360° right turn circle maneuver on the ramp.



View of airplane circling on ramp.



View of airplane completing 360° right turn on the ramp.



Accident Takeoff. Rotation - first sign nose coming off runway. (Approaching 1,000 ft markers)



Accident Takeoff. Rotation - immediate left bank observed.



Few seconds after rotation, left roll and turn observed.



Left roll increases, nearly 90° knife edge bank. Left turn continues.



Left wing roll and turn continues, altitude loss observed.



Left wing impacts terrain first.



Left wing drags through the terrain, pulling nose downward into terrain.



Explosion observed.