



Survival Factors Factual Report Attachment-
Scene Photographs

Cleveland, Ohio

RRD23LR007

(6 pages)



Figure 1 Photo looking westbound, in the direction of travel of the train, towards the industry crossing and showing the final rest position of the truck along side the right side of the train. (Source: NTSB)



Figure 2 Photograph showing a closeup of the dump truck the final rest position adjacent to the right side of the rail car. (Source: NTSB)



Figure 3 Photograph showing a closeup of the damage to the rear running board where the conductor was standing and the side of the rail car resulting from the impact with the dump truck (Source: NTSB)



Figure 4 A closeup photograph of the side of the rail car damage by the collision with the dump truck. In the background, the conductor's lantern is seen underneath the rail car. (Source: NTSB)



Figure 5 Photograph showing a closeup of the front of the dump truck and its proximity to the rail car at final rest. Damage seen to the side of the rail car occurred during the accident. (Source: NTSB)



Figure 6 The photograph shows a view of the accident scene, looking eastward, the approach road to the crossing on the right and the proximity of the utility pole and the overhead lighting to the left (Source: NTSB)



Figure 7 Photograph showing the angle of approach of the dump truck to the crossing. (Source: NTSB)



Figure 8 Photograph showing the line of sight of the driver and the angle of the track as the train approaches from the east traveling west (from right to left in the photo). (Source: NTSB)



Figure 9 Photograph showing the right side of the dump truck and the obstacles limiting the driver's ability to see the train approaching from the right. (Source: NTSB)