

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
Inspection Date :2020/09/29																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM								2020/09/29	005437350 50000002
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/09/29	005854429 10000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/09/29	005854700 10000002
Inspection Date :2020/10/02																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100114 4315100 01	0133A9 Loose, worn, missing adj braces	1016.698	RAIL BRACES	.00	No add'l action/Trk OK for posted speed		2020/10/02	005854429 10000004
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100114 4315200 01	0133A14 Loose/wor n/missing gr component	1016.698	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed		2020/10/02	005854429 10000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/02	005854700 10000003
Inspection Date :2020/10/07																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM								2020/10/07	005927678 60000002
0036	1011.975	1023.450	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/07	005979840 80000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/07	005980003 40000002
Inspection Date :2020/10/09																		

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/09	005979840 800000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/09	005980003 400000004
Inspection Date :2020/10/13																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100115 1008800 01	0133A15 Fastening s not intact/maint ained	1022.268	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	10/09/2020 13:44:22 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :10/09/2020 CREATED TIME: 12:29:32 PM NEED A CASTLE. WELDED ON FOR E-CLIP ON FROG .	2020/10/13	006106076 200000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/13	006106007 600000002
Inspection Date :2020/10/15																		

Total Record count: 14

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100115 1008800 01	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	10/09/2020 13:44:22 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/09/2020 CREATED TIME: 12:29:32 PM NEED A CASTLE. WELDED ON FOR E-CLIP ON FROG .	2020/10/15	006106076 200000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				STUBBS, WILLIAM								2020/10/15	006106007 600000004
Inspection Date :2020/10/20																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100115 5374300 01	0121A2 Not structurally sound (cwr)	1029.005	JOINT BAR	.00	No add'l action/Trk OK for posted speed	10/16/2020 17:10:29 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/16/2020 CREATED TIME: 2:40:11 PM NEED A 136 1/4. HEAD LOSS IJ .	2020/10/20	006230510 100000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/20	006230668 200000002
Inspection Date :2020/10/21																		
0036	1014.736	1014.736	1014.736_ PJNT_L						STUBBS, WILLIAM								2020/10/21	005453740 700000002
0036	1014.736	1014.736	1014.736_ PJNT_R						STUBBS, WILLIAM								2020/10/21	005453795 200000002
0036	1014.853	1014.853	1014.853_ PJNT_L						STUBBS, WILLIAM								2020/10/21	004658661 200000002
0036	1014.853	1014.853	1014.853_ PJNT_L						STUBBS, WILLIAM								2020/10/21	005453766 000000002
0036	1014.853	1014.853	1014.853_ PJNT_R						STUBBS, WILLIAM								2020/10/21	004658660 300000002
0036	1014.853	1014.853	1014.853_ PJNT_R						STUBBS, WILLIAM								2020/10/21	005453761 600000002
Inspection Date :2020/10/23																		
0036	1011.975	1023.100	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/23	006230510 100000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/23	006230668 200000004
Inspection Date :2020/10/25																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK		COLD		STUBBS, WILLIAM	0100115 5374300 01	0121A2 Not structurally sound (cwr)	1029.005	JOINT BAR	.00	No add'l action/Trk OK for posted speed	10/16/2020 17:10:29 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :10/16/2020 CREATED TIME: 2:40:11 PM NEED A 136 1/4. HEAD LOSS IJ .	2020/10/25	006365124 700000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK		COLD		STUBBS, WILLIAM								2020/10/25	006365298 300000002
Inspection Date :2020/10/29																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100115 5374300 01	0121A2 Not structurally sound (cwr)	1029.005	JOINT BAR	.00	No add'l action/Trk OK for posted speed	10/16/2020 17:10:29 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/16/2020 CREATED TIME: 2:40:11 PM NEED A 136 1/4. HEAD LOSS IJ .	2020/10/29	006365124 700000012
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4001900 01	0133A14 Loose/wor n/missing gr component	1022.913	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	10/27/2020 13:51:45 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/27/2020 CREATED TIME: 12:40:46 PM BROKEN WELD. ON MIDDLE GAUGE PLATE NORTH RAIL .	2020/10/29	006365124 700000012

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4098500 01	0133A10 Missing switch, frog, gr plates	1023.111	SW PLATES	.00	No add'l action/Trk OK for posted speed	10/27/2020 16:04:15 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :10/27/2020 CREATED TIME: 2:52:42 PM 2 BROKEN. PANDROL PLATES MARKED WITH GREEN RIBBON .	2020/10/29	006365124 700000012
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/10/29	006365298 300000006
Inspection Date :2020/11/03																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4001900 01	0133A14 Loose/wor n/missing gr component	1022.913	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	10/27/2020 13:51:45 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :10/27/2020 CREATED TIME: 12:40:46 PM BROKEN WELD. ON MIDDLE	2020/11/03	006497036 900000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4001900 01	0133A14 Loose/wor n/missing gr component	1022.913				GAUGE PLATE NORTH RAIL .		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4098500 01	0133A10 Missing switch, frog, gr plates	1023.111	SW PLATES	.00	No add'l action/Trk OK for posted speed	10/27/2020 16:04:15 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/27/2020 CREATED TIME: 2:52:42 PM 2 BROKEN. PANDROL PLATES MARKED WITH GREEN RIBBON .	2020/11/03	006497036 900000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/03	006497096 000000002

Inspection Date :2020/11/05

Total Record count: 35

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100116 4001900 01	0133A14 Loose/worn/missing gr component	1022.913	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	10/27/2020 13:51:45 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/27/2020 CREATED TIME: 12:40:46 PM BROKEN WELD. ON MIDDLE GAUGE PLATE NORTH RAIL .	2020/11/05	006497036 900000003
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100116 4098500 01	0133A10 Missing switch, frog, gr plates	1023.111	SW PLATES	.00	No add'l action/Trk OK for posted speed	10/27/2020 16:04:15 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :10/27/2020 CREATED TIME: 2:52:42 PM 2 BROKEN. PANDROL PLATES MARKED WITH GREEN RIBBON .	2020/11/05	006497036 900000003

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/05	006497096 00000003
Inspection Date :2020/11/10																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM								2020/11/10	006499806 30000002
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100116 4001900 01	0133A14 Loose/wor n/missing gr component	1022.913	GUARD RAIL MATERI AL	.00	Defect repaired since last inspection	10/27/2020 13:51:45 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :10/27/2020 CREATED TIME: 12:40:46 PM BROKEN WELD. ON MIDDLE GAUGE PLATE NORTH RAIL .	2020/11/10	006622701 20000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/10	006622570 50000002
Inspection Date :2020/11/12																		
0036	1011.975	1041.611	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/12	006622701 20000004

Total Record count: 42

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/12	006622570 500000004
Inspection Date :2020/11/17																		
0036	1011.975	1035.900	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/17	006740679 500000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/17	006740845 100000002
Inspection Date :2020/11/19																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/19	006740679 500000005
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/19	006740845 100000003
Inspection Date :2020/11/23																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/23	006863791 400000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/23	006863879 400000002
Inspection Date :2020/11/25																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/25	006863791 400000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/11/25	006863879 400000003
Inspection Date :2020/12/02																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/02	006990442 400000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/02	006990176 700000002
Inspection Date :2020/12/03																		

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM	0100119 3062500 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	Scheduled for repair - 30 days or less	12/03/2020 14:23:31 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/03/2020 CREATED TIME: 1:11:47 PM 2 GUARD RAIL. FASTNERS ARE LOOSE ON MAIN AND 1 ON TURNOUT. TURNOUT NEEDS A.* DJUSTED].	2020/12/03	007029021 200000002

Inspection Date :2020/12/04

Total Record count: 54

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 3062500 01	0133A14 Loose/worn/missing gr component	1014.745	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/03/2020 14:23:31 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/03/2020 CREATED TIME: 1:11:47 PM 2 GUARD RAIL. FASTNERS ARE LOOSE ON MAIN AND 1 ON TURNOUT. TURNOUT NEEDS A.* DJUSTED .	2020/12/04	006990442 400000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2020/12/04	006990176 700000004

Inspection Date :2020/12/08

Total Record count: 56

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100119 3062500 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	Defect repaired since last inspection	12/03/2020 14:23:31 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/03/2020 CREATED TIME: 1:11:47 PM 2 GUARD RAIL. FASTNERS ARE LOOSE ON MAIN AND 1 ON TURNOUT. TURNOUT NEEDS A.* DJUSTED .	2020/12/08	007109852 10000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/08	007110120 10000002
Inspection Date :2020/12/10																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/10	007109852 10000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/10	007110120 10000004

Inspection Date :2020/12/15

Total Record count: 60

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	010011974648001	0133A14 Loose/worn/missing gr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/10/2020 14:57:04 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/10/2020 CREATED TIME: 1:44:33 PM 2 LOOSE GUARD. RAIL FASTNERS AND NEEDS ADJUSTMENT .	2020/12/15	00722215800000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	010011980238001	0133A14 Loose/worn/missing gr component	1023.111	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 10:52:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:40:55 AM LOOSE GUARD. RAIL FASTENERS, GUARD RAIL NEEDS ADJUSTED	2020/12/15	00722215800000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8023800 01	0133A14 Loose/worn/missing gr component	1023.111				.		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8043200 01	0133A14 Loose/worn/missing gr component	1023.517	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 11:28:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:59:32 AM BROKEN GAUGE. PLATE DUE TO BAD 13' TIE .	2020/12/15	007222158 000000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8112700 01	0133A14 Loose/worn/missing gr component	1034.691	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 14:03:37 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 12:52:21 PM GUARD RAIL. NEEDS ADJUSTED, AND POINT	2020/12/15	007222158 000000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8112700 01	0133A14 Loose/worn/missing gr component	1034.691				NEEDS TO BE RADIUSED II.		
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2020/12/15	007222330 900000002
Inspection Date :2020/12/17																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8023800 01	0133A14 Loose/worn/missing gr component	1023.111	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 10:52:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:40:55 AM LOOSE GUARD. RAIL FASTENERS, GUARD RAIL NEEDS ADJUSTED II.	2020/12/17	007222158 000000004

Total Record count: 66

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8043200 01	0133A14 Loose/worn/missing gr component	1023.517	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 11:28:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:59:32 AM BROKEN GAUGE. PLATE DUE TO BAD 13' TIE .	2020/12/17	007222158 000000004
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100119 8112700 01	0133A14 Loose/worn/missing gr component	1034.691	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 14:03:37 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :12/11/2020 CREATED TIME: 12:52:21 PM GUARD RAIL. NEEDS ADJUSTED, AND POINT NEEDS TO BE RADIUSED .	2020/12/17	007222158 000000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2020/12/17	007222330 900000004
Inspection Date :2020/12/21																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				ERIKSON, DAVID	0100119 8023800 01	0133A14 Loose/wor n/missing gr component	1023.111	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	12/11/2020 10:52:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:40:55 AM LOOSE GUARD. RAIL FASTENER S, GUARD RAIL NEEDS ADJUSTED .	2020/12/21	007326277 200000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				ERIKSON, DAVID	0100119 8043200 01	0133A14 Loose/wor n/missing gr component	1023.517	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	12/11/2020 11:28:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:59:32 AM BROKEN	2020/12/21	007326277 200000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100119 8043200 01	0133A14 Loose/worn/missing gr component	1023.517				GAUGE. PLATE DUE TO BAD 13' TIE .		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100119 8112700 01	0133A14 Loose/worn/missing gr component	1034.691	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	12/11/2020 14:03:37 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/11/2020 CREATED TIME: 12:52:21 PM GUARD RAIL. NEEDS ADJUSTED, AND POINT NEEDS TO BE RADIUSED .	2020/12/21	007326277 200000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/WALK				ERIKSON, DAVID								2020/12/21	007326239 100000002

Inspection Date :2020/12/23

Total Record count: 73

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100119 8043200 01	0133A14 Loose/wor n/missing gr component	1023.517	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	12/11/2020 11:28:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:59:32 AM BROKEN GAUGE. PLATE DUE TO BAD 13' TIE .	2020/12/23	007326277 200000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/WALK				ERIKSON, DAVID								2020/12/23	007326239 100000003
Inspection Date :2020/12/28																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100119 8043200 01	0133A14 Loose/wor n/missing gr component	1023.517	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	12/11/2020 11:28:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :12/11/2020 CREATED TIME: 9:59:32 AM BROKEN GAUGE. PLATE DUE TO BAD 13' TIE .	2020/12/28	007432583 400000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2020/12/28	007432839 600000002
Inspection Date :2020/12/30																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2020/12/30	007432583 400000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2020/12/30	007432839 600000003
Inspection Date :2021/01/05																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/05	007532446 700000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/05	007532617 700000002
Inspection Date :2021/01/07																		
0036	1011.975	1056.300	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/07	007532446 700000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/07	007532617 700000004
Inspection Date :2021/01/12																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/12	007630251 100000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/12	007630416 500000002
Inspection Date :2021/01/15																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/15	007630251 100000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/15	007630416 500000006
Inspection Date :2021/01/19																		

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/19	007729824 600000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/19	007729761 400000002
Inspection Date :2021/01/21																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/21	007729824 600000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/21	007729761 400000004
Inspection Date :2021/01/26																		
0036	1011.975	1031.171	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/26	007835861 700000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/26	007836041 600000002
Inspection Date :2021/01/28																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	Scheduled for repair - 30 days or less	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON	2021/01/28	007502817 800000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745				TURNOUT].		
Inspection Date :2021/01/29																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT].	2021/01/29	007835861 700000005
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/01/29	007836041 600000004

Inspection Date :2021/02/03

Total Record count: 96

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1026.400	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT .	2021/02/03	007938342 100000003

Total Record count: 97

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1026.400	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 2726400 01	0133A15 Fastening s not intact/maint ained	1023.517	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	01/29/2021 15:19:00 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :01/29/2021 CREATED TIME: 2:02:25 PM NEEDS 10 E. CLIPS AND PLATES RE SPIKED TO TIES BETWEEN THE HEEL BLOCK AND.* FROG ON NORTH RAIL OF TURNOUT].	2021/02/03	007938342 100000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/03	007938657 700000002

Inspection Date :2021/02/06

Total Record count: 99

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT .	2021/02/06	007938342 100000004

Total Record count: 100

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 2726400 01	0133A15 Fastening s not intact/maint ained	1023.517	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	01/29/2021 15:19:00 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :01/29/2021 CREATED TIME: 2:02:25 PM NEEDS 10 E. CLIPS AND PLATES RE SPIKED TO TIES BETWEEN THE HEEL BLOCK AND.* FROG ON NORTH RAIL OF TURNOUT].	2021/02/06	007938342 100000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/06	007938657 700000003

Inspection Date :2021/02/08

Total Record count: 102

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT .	2021/02/08	008047945 100000002

Total Record count: 103

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 2726400 01	0133A15 Fastening s not intact/maint ained	1023.517	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	01/29/2021 15:19:00 CST WILLIAM STUBBS (B179096). B179096 CREATED DATE :01/29/2021 CREATED TIME: 2:02:25 PM NEEDS 10 E. CLIPS AND PLATES RE SPIKED TO TIES BETWEEN THE HEEL BLOCK AND.* FROG ON NORTH RAIL OF TURNOUT].	2021/02/08	008047945 100000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/08	008048085 400000002

Inspection Date :2021/02/10

Total Record count: 105

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT .	2021/02/10	008047945 100000003

Total Record count: 106

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 2726400 01	0133A15 Fastening s not intact/maint ained	1023.517	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	01/29/2021 15:19:00 CST WILLIAM STUBBS (B179096). B179096 CREATED DATE :01/29/2021 CREATED TIME: 2:02:25 PM NEEDS 10 E. CLIPS AND PLATES RE SPIKED TO TIES BETWEEN THE HEEL BLOCK AND.* FROG ON NORTH RAIL OF TURNOUT].	2021/02/10	008047945 100000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/10	008048085 400000003
Inspection Date :2021/02/12																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		COLD		STUBBS, WILLIAM								2021/02/12	008047945 100000004
Inspection Date :2021/02/14																		

Total Record count: 109

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100124 0084400 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	01/28/2021 12:43:41 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/28/2021 CREATED TIME: 11:08:37 AM 2 GUARD RAIL. BRACES ARE LOOSE ON MAIN SIDE AND 1 ON TURNOUT .	2021/02/14	008152270 10000002

Total Record count: 110

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100124 2726400 01	0133A15 Fastenings not intact/maintained	1023.517	SW CLIPS FASTENINGS	.00	No additional action/Trk OK for posted speed	01/29/2021 15:19:00 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :01/29/2021 CREATED TIME: 2:02:25 PM NEEDS 10 E. CLIPS AND PLATES RE SPIKED TO TIES BETWEEN THE HEEL BLOCK AND.* FROG ON NORTH RAIL OF TURNOUT .	2021/02/14	008152270 100000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				STUBBS, WILLIAM								2021/02/14	008152398 300000002
Inspection Date :2021/02/18																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID								2021/02/18	008152270 100000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				ERIKSON, DAVID								2021/02/18	008152398 300000003
Inspection Date :2021/02/23																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/02/23	008252847 500000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/23	008253012 200000002
Inspection Date :2021/02/25																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100126 4887300 01	0133A14 Loose/wor n/missing gr component	1048.082	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	02/24/2021 13:26:01 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/24/2021 CREATED TIME: 12:14:24 PM 2 LOOSE GUARD. RAIL BRACES, MARKED WITH ORANGE RIBBON .	2021/02/25	008252847 500000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/02/25	008253012 200000003
Inspection Date :2021/02/26																		

Total Record count: 118

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1014.745	1014.745_TURN_#20_3598E_136LB_LP OWER			YES			STUBBS, WILLIAM	0100126 9299700 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	Scheduled for repair - 30 days or less	02/26/2021 15:12:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :02/26/2021 CREATED TIME: 1:51:10 PM COMPONE NTS IN. GUARD RAIL WONT STAY TIGHT, NEED NEW GUARD RAIL .	2021/02/26	007957310 300000002
Inspection Date :2021/03/02																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100126 4887300 01	0133A14 Loose/wor n/missing gr component	1048.082	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	02/24/2021 13:26:01 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :02/24/2021 CREATED TIME: 12:14:24 PM 2 LOOSE GUARD. RAIL BRACES, MARKED	2021/03/02	008371952 700000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126488730001	0133A14 Loose/worn/missing gr component	1048.082				WITH ORANGE RIBBON .		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126910460001	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 11:38:39 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 10:27:09 AM CASTLE NEEDS. TO BE WELDED ON AT FROG .	2021/03/02	00837195270000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126929970001	0133A14 Loose/worn/missing gr component	1014.745	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 15:12:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 1:51:10 PM COMPONENTS IN. GUARD RAIL WONT	2021/03/02	00837195270000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126929970001	0133A14 Loose/worn/missing gr component	1014.745				STAY TIGHT, NEED NEW GUARD RAIL .		
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/02	00837220800000002
Inspection Date :2021/03/04																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126910460001	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 11:38:39 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 10:27:09 AM CASTLE NEEDS. TO BE WELDED ON AT FROG .	2021/03/04	00837195270000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/04	00837220800000003
Inspection Date :2021/03/10																		

Total Record count: 125

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126 9104600 01	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 11:38:39 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 10:27:09 AM CASTLE NEEDS. TO BE WELDED ON AT FROG .	2021/03/10	008497162 900000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/10	008497308 900000002
Inspection Date :2021/03/12																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126 9104600 01	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 11:38:39 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 10:27:09 AM CASTLE NEEDS. TO BE WELDED	2021/03/12	008497162 900000003

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126 9104600 01	0133A15 Fastenings not intact/maintained	1022.268				ON AT FROG .		
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/12	008497308 900000003
Inspection Date :2021/03/17																		
0036	1011.975	1023.000	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100126 9104600 01	0133A15 Fastenings not intact/maintained	1022.268	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	02/26/2021 11:38:39 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :02/26/2021 CREATED TIME: 10:27:09 AM CASTLE NEEDS. TO BE WELDED ON AT FROG .	2021/03/17	008631336 000000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/17	008631494 600000002
Inspection Date :2021/03/19																		
0036	1014.745	1014.745	1014.745_TURN_#20_3598E_136LB_L_POWER			YES			STUBBS, WILLIAM								2021/03/19	008396005 200000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	010012808478001	0133A14 Loose/workn/missinggr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	03/12/2021 11:16:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :03/12/2021 CREATED TIME: 9:38:02 AM 2 LOOSE GUARD. RAIL BRACES-NEEDS NEW HARDWARE .*	2021/03/19	00863133600000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/wor n/missing gr component	1048.082				ON 03-25-21, DISPARITY IN REPORTIN G DUE TO C.* OMPUTER ISSUE .		
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/03/19	008631494 600000003

Inspection Date :2021/03/23

Total Record count: 134

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/workn/missing gr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	03/12/2021 11:16:36 CST WILLIAM STUBBS (B179096). B179096 CREATED DATE :03/12/2021 CREATED TIME: 9:38:02 AM 2 LOOSE GUARD. RAIL BRACES- NEEDS NEW HARDWARE .* ----- ----- -----.* 03/30/2021 07:23:55 CST RAINER HOFFMAN (B037678). B037678 CREATED DATE :03/30/2021 CREATED TIME: 6:23:05 AM REPAIRED BY. CUT BANK SECTION	2021/03/23	008742943 900000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/wor n/missing gr component	1048.082				ON 03-25-21, DISPARITY IN REPORTIN G DUE TO C.* OMPUTER ISSUE .		
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/03/23	008743213 40000002

Inspection Date :2021/03/25

Total Record count: 136

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/work n/missing gr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	03/12/2021 11:16:36 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :03/12/2021 CREATED TIME: 9:38:02 AM 2 LOOSE GUARD. RAIL BRACES- NEEDS NEW HARDWARE .* ----- ----- -----.* 03/30/2021 07:23:55 CST RAINER HOFFMAN (B037678). * B037678 CREATED DATE :03/30/2021 CREATED TIME: 6:23:05 AM REPAIRED BY. CUT BANK SECTION	2021/03/25	008742943 900000003

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/wor n/missing gr component	1048.082				ON 03-25-21, DISPARITY IN REPORTIN G DUE TO C.* OMPUTER ISSUE .		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100128 8179900 01	0133A10 Missing switch, frog, gr plates	1027.286	SW PLATES	.00	No add'l action/Trk OK for posted speed	03/23/2021 11:03:17 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :03/23/2021 CREATED TIME: 9:48:43 AM BROKEN. PANDROLL PLATE BETWEEN HEEL BLOCK OF SWITCH POINTS AND FROG .	2021/03/25	008742943 900000003

Total Record count: 138

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128 9415700 01	0133A15 Fastenings not intact/maintained	1023.517	GUARD RAIL MATERIAL	.00	Defect repaired since last inspection	03/24/2021 13:48:46 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :03/24/2021 CREATED TIME: 12:47:55 PM BROKEN GAUGE. PLATE DUE TO BAD 13' TIE .	2021/03/25	008742943 900000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/25	008743213 400000003

Inspection Date :2021/03/29

Total Record count: 140

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128 0847800 01	0133A14 Loose/workn/missing gr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	03/12/2021 11:16:36 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :03/12/2021 CREATED TIME: 9:38:02 AM 2 LOOSE GUARD. RAIL BRACES-NEEDS NEW HARDWARE .*	2021/03/29	008849427 600000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128084780001	0133A14 Loose/worn/missing gr component	1048.082				ON 03-25-21, DISPARITY IN REPORTING DUE TO C.* COMPUTER ISSUE .		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100128817990001	0133A10 Missing switch, frog, gr plates	1027.286	SW PLATES	.00	No add'l action/Trk OK for posted speed	03/23/2021 11:03:17 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :03/23/2021 CREATED TIME: 9:48:43 AM BROKEN. PANDROLL PLATE BETWEEN HEEL BLOCK OF SWITCH POINTS AND FROG .	2021/03/29	00884942760000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				STUBBS, WILLIAM								2021/03/29	00884967570000002

Inspection Date :2021/03/31

Total Record count: 143

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				ERIKSON, DAVID	0100128 8179900 01	0133A10 Missing switch, frog, gr plates	1027.286	SW PLATES	.00	No add'l action/Trk OK for posted speed	03/23/2021 11:03:17 CST WILLIAM STUBBS (B179096). B179096 CREATED DATE :03/23/2021 CREATED TIME: 9:48:43 AM BROKEN. PANDROLL PLATE BETWEEN HEEL BLOCK OF SWITCH POINTS AND FROG .	2021/03/31	008849427 600000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				ERIKSON, DAVID								2021/03/31	008849675 700000003

Inspection Date :2021/04/06

Total Record count: 145

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100128 8179900 01	0133A10 Missing switch, frog, gr plates	1027.286	SW PLATES	.00	No add'l action/Trk OK for posted speed	03/23/2021 11:03:17 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :03/23/2021 CREATED TIME: 9:48:43 AM BROKEN. PANDROLL PLATE BETWEEN HEEL BLOCK OF SWITCH POINTS AND FROG .	2021/04/06	008978846 600000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/06	008978981 900000002
Inspection Date :2021/04/08																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/08	008978846 600000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/08	008978981 900000003
Inspection Date :2021/04/13																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/13	009086084 200000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/13	009086328 300000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
Inspection Date :2021/04/15																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/15	009086084 200000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/15	009086328 300000003
Inspection Date :2021/04/20																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/20	009192398 700000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6124100 01	0109B2 Ties not effectively distributed	1047.908	NON CLASS TIE DEFECT	.00	Scheduled for repair - 30 days or less	04/20/2021 15:50:10 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:47:24 PM EAST SIDE OF. BRIDGE NEED 10- 10' TIES .	2021/04/20	009192398 700000003

Total Record count: 155

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6124900 01	0109B2 Ties not effectively distributed	1047.918	NON CLASS TIE DEFECT	.00	Scheduled for repair - 30 days or less	04/20/2021 15:50:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:48:39 PM WEST SIDE OF. BRIDGE NEED 10-10' TIES .	2021/04/20	009192398 70000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/20	009192685 10000002
Inspection Date :2021/04/22																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			STUBBS, WILLIAM								2021/04/22	008903375 00000002

Total Record count: 158

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6124100 01	0109B2 Ties not effectively distributed	1047.908	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:10 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:47:24 PM EAST SIDE OF. BRIDGE NEED 10- 10' TIES .	2021/04/22	009192398 700000004
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6124900 01	0109B2 Ties not effectively distributed	1047.918	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:48:39 PM WEST SIDE OF. BRIDGE NEED 10-10' TIES .	2021/04/22	009192398 700000004

Total Record count: 160

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6894700 01	0137E Severe frog condition	1056.062	FROG GUARD RAIL CONDITI ON	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:13:11 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 7:53:45 AM WING NEEDS. WELDED AND POINT NEEDS RADIUSED].	2021/04/22	009192398 700000004
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 6899400 01	0133A15 Fastening s not intact/maint ained	1056.062	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:13:08 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 7:52:53 AM BROKEN GAUGE. PLATE].	2021/04/22	009192398 700000004

Total Record count: 162

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100131690190001	0137E Severe frog condition	1057.995	FROG GUARD RAIL CONDITION	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:13:16 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 7:56:11 AM WING NEEDS TO. BE WELDED, AND RADIUSED].	2021/04/22	009192398700000004
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100131692850001	0133A15 Fastenings not intact/maintained	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:40:07 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 8:28:09 AM BROKEN GAUGE. PLATE MAIN SIDE AT POINT].	2021/04/22	009192398700000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	010013169339001	0133A14 Loose/worn/missing gr component	1048.082	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:40:09 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 8:29:28 AM GUARD RAIL. NEEDS SHIMS ADJUSTED OUT .	2021/04/22	00919239870000004
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	010013169729001	0133A14 Loose/worn/missing gr component	1046.267	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/21/2021 10:21:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 9:09:46 AM GUARD RAIL. NEEDS SHIMS ADJUSTED OUT TO 54 5/8 .	2021/04/22	00919239870000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/22	009192685 100000003
Inspection Date :2021/04/27																		
0036	1011.975	1023.000	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 8060300 01	0133A15 Fastening s not intact/maint ained	1016.698	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/04/27	009299066 600000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				STUBBS, WILLIAM								2021/04/27	009299303 500000002
Inspection Date :2021/04/29																		
0036	1011.975	1023.300	MAIN_0	TVS	HYRAIL/ WALK				STUBBS, WILLIAM	0100131 8060300 01	0133A15 Fastening s not intact/maint ained	1016.698	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE.	2021/04/29	009299066 600000005

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1023.300	MAIN_0	TVS	HYRAIL/WALK				STUBBS, WILLIAM	0100131806030001	0133A15 Fastenings not intact/maintained	1016.698				PLATE .		
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	OBS	HYRAIL/WALK				STUBBS, WILLIAM								2021/04/30	00929930350000003
Inspection Date :2021/05/05																		
0036	1011.975	1022.000	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100131806030001	0133A15 Fastenings not intact/maintained	1016.698	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/05/05	00941932700000003
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/05/05	00941969190000002
Inspection Date :2021/05/07																		

Total Record count: 173

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1041.600	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100131 8060300 01	0133A15 Fastening s not intact/maint ained	1016.698	GUARD RAIL MATERI AL	.00	No add'l action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/05/07	009419327 000000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/07	009419691 900000003
Inspection Date :2021/05/10																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100131 6124100 01	0109B2 Ties not effectively distributed	1047.908	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:10 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:47:24 PM EAST SIDE OF. BRIDGE NEED 10- 10' TIES .	2021/05/10	009521002 900000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100131 6124900 01	0109B2 Ties not effectively distributed	1047.918	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:48:39 PM WEST SIDE OF BRIDGE NEED 10-10' TIES .	2021/05/10	009521002 900000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100131 6894700 01	0137E Severe frog condition	1056.062	FROG GUARD RAIL CONDITON	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:13:11 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 7:53:45 AM WING NEEDS WELDED AND POINT NEEDS RADIUSED .	2021/05/10	009521002 900000002

Total Record count: 178

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	010013168994001	0133A15 Fastenings not intact/maintained	1056.062	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/21/2021 09:13:08 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/21/2021 CREATED TIME: 7:52:53 AM BROKEN GAUGE. PLATE .	2021/05/10	00952100290000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	010013180603001	0133A15 Fastenings not intact/maintained	1016.698	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/05/10	00952100290000002
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/05/10	00952157170000002

Inspection Date :2021/05/12

Total Record count: 181

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1051.370	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100131 6124100 01	0109B2 Ties not effectively distributed	1047.908	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:10 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:47:24 PM EAST SIDE OF. BRIDGE NEED 10- 10' TIES .	2021/05/12	009521002 900000003
0036	1011.975	1051.370	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100131 6124900 01	0109B2 Ties not effectively distributed	1047.918	NON CLASS TIE DEFECT	.00	No add'l action/Trk OK for posted speed	04/20/2021 15:50:12 CST WILLIAM STUBBS (B179096). * B179096 CREATED DATE :04/20/2021 CREATED TIME: 2:48:39 PM WEST SIDE OF. BRIDGE NEED 10-10' TIES .	2021/05/12	009521002 900000003

Total Record count: 183

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1051.370	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100131 8060300 01	0133A15 Fastenings not intact/maintained	1016.698	GUARD RAIL MATERIAL	.00	No additional action/Trk OK for posted speed	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/05/12	009521002 900000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/05/12	009521571 700000003
Inspection Date :2021/05/17																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100131 8060300 01	0133A15 Fastenings not intact/maintained	1016.698	GUARD RAIL MATERIAL	.00	Defect repaired since last inspection	04/22/2021 14:02:12 CST WILLIAM STUBBS (B179096).* B179096 CREATED DATE :04/22/2021 CREATED TIME: 12:50:41 PM BROKEN GAUGE. PLATE .	2021/05/17	009623105 300000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/17	009623207 300000002
Inspection Date :2021/05/21																		
0036	1011.975	1047.600	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/21	009623105 300000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/21	009623207 300000003
Inspection Date :2021/05/25																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/25	009734909 000000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/05/25	009735115 800000002
Inspection Date :2021/05/26																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			JOHNSON, GREGORY								2021/05/26	009380909 700000002
Inspection Date :2021/05/27																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100135 5895800 01	0127A3 insufficient fasteners at joint	1038.958	RAIL FASTE NERS ANCHO RS	.00	Scheduled for repair - 30 days or less	05/27/2021 11:59:27 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :05/27/2021 CREATED TIME: 10:48:00 AM NEW IJ PLATES. NEED	2021/05/27	009734909 000000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100135589580001	0127A3 insufficient fasteners at joint	1038.958				LAGS .		
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/05/27	009735115800000003
Inspection Date :2021/06/01																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK		HOT		JOHNSON, GREGORY								2021/06/01	009825130300000003
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/06/01	009825405000000002
Inspection Date :2021/06/02																		
0036	1011.975	1056.500	MAIN_0	TVS	HYRAIL/WALK		HOT		JOHNSON, GREGORY								2021/06/02	009825130300000007
Inspection Date :2021/06/03																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK		HOT		JOHNSON, GREGORY	0100135589580001	0127A3 insufficient fasteners at joint	1038.958	RAIL FASTENERS ANCHORS	.00	No add'l action/Trk OK for posted speed	05/27/2021 11:59:27 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :05/27/2021 CREATED TIME: 10:48:00 AM NEW IJ PLATES. NEED LAGS .	2021/06/03	009825130300000012
0036	1014.745	1016.698	SDNG_1014.745_3598_BUELOW	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/06/03	009825405000000003

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
Inspection Date :2021/06/04																		
0036	1011.975	1066.300	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/06/04	009825130 300000015
Inspection Date :2021/06/08																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/08	009930549 300000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/08	009930348 900000002
Inspection Date :2021/06/10																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/10	009930549 300000005
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/10	009930348 900000003
Inspection Date :2021/06/14																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			NO			JOHNSON, GREGORY	0100135 9514600 01	0133A14 Loose/wor n/missing gr component	1014.745	GUARD RAIL MATERI AL	.00	Repaired Before Traffic	06/14/2021 16:39:02 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/14/2021 CREATED TIME: 3:22:47 PM MISSING J. HOOK. .	2021/06/14	009841633 500000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/14	010031611 400000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/06/14	010031611 400000003

Total Record count: 207

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/14	010031790 700000002
Inspection Date :2021/06/15																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/15	010031611 400000007
Inspection Date :2021/06/18																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/18	010031611 400000011
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/18	010031790 700000004
Inspection Date :2021/06/22																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/22	010134851 900000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/22	010135122 500000002
Inspection Date :2021/06/24																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/24	010134851 900000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/24	010135122 500000004
Inspection Date :2021/06/28																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			JOHNSON, GREGORY								2021/06/28	009841633 500000004

Total Record count: 216

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138679470001	0133A14 Loose/worn/missing gr component	1057.995	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:18 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:32:44 PM JHOOKS KNOCKED. OF AND GUARD RAIL NEEDS ADJUSTED.	2021/06/28	010236506400000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138680020001	0133A14 Loose/worn/missing gr component	1057.995	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:20 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:36:17 PM JHOOKS KNOCKED. OFF GUARD RAIL, RAIL NEEDS ADJUSTED.	2021/06/28	010236506400000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138680020001	0133A14 Loose/worn/missing gr component	1057.995				.		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138680350001	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/06/28	01023650640000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138680450001	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTENINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/06/28	01023650640000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/28	010236700 200000002
Inspection Date :2021/06/29																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/06/29	010236506 400000004
Inspection Date :2021/06/30																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/06/30	010236506 400000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/06/30	010236700 200000004
Inspection Date :2021/07/01																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY	0100138 6803500 01	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/07/01	010236506 400000008

Total Record count: 225

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY	0100138 6804500 01	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/07/01	010236506 400000008
Inspection Date :2021/07/02																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/07/02	010236506 400000010
Inspection Date :2021/07/06																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100138 6803500 01	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/07/06	010351419 000000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100138 6804500 01	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/07/06	010351419 000000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/06	010351533 600000002
Inspection Date :2021/07/09																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100138 6803500 01	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/07/09	010351419 000000004

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100138 6804500 01	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTENINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/07/09	010351419 000000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/07/09	010351533 600000004
Inspection Date :2021/07/12																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100138 6803500 01	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500).* B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/07/12	010451009 900000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100138 6804500 01	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/07/12	010451009 900000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/WALK				ERIKSON, DAVID								2021/07/12	010451232 200000002
Inspection Date :2021/07/14																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				ERIKSON, DAVID	0100138 6803500 01	0133A10 Missing switch, frog, gr plates	1056.062	SW PLATES	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:15 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 7:18:21 PM BROKEN GAGE. PLATE WELD. .	2021/07/14	010451009 900000008

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				ERIKSON, DAVID	0100138 6804500 01	0133A1 Loose, worn, missing switch clips	1048.082	SW CLIPS FASTE NINGS	.00	No add'l action/Trk OK for posted speed	06/26/2021 21:31:06 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :06/26/2021 CREATED TIME: 6:49:43 PM FROG PLATE HAS. A BROKEN ECLIP CASTLE. .	2021/07/14	010451009 900000008
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				ERIKSON, DAVID								2021/07/14	010451232 200000008
Inspection Date :2021/07/17																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK		HOT		JOHNSON, GREGORY								2021/07/17	010451009 900000024
Inspection Date :2021/07/20																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/21	010550472 500000002
Inspection Date :2021/07/21																		
0036	1011.975	1022.400	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/21	010550472 500000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/21	010550397 300000002
Inspection Date :2021/07/23																		
0036	1011.975	1056.400	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/23	010550472 500000011

Total Record count: 244

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/23	010550397 300000003
Inspection Date :2021/07/27																		
0036	1011.975	1022.500	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/27	010652812 600000005
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/27	010652868 800000002
Inspection Date :2021/07/30																		
0036	1014.745	1014.745	1014.745_ TURN_#20 _3598E_1 36LB_L_P OWER			YES			JOHNSON, GREGORY								2021/07/30	010283255 700000002
0036	1011.975	1035.000	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/30	010652812 600000027
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/07/30	010652868 800000003
Inspection Date :2021/08/02																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100140 8784100 01	0133A12 Loose, worn, missing frog bolts	1057.995	FROG BOLTS	.00	No add'l action/Trk OK for posted speed	07/21/2021 21:02:01 CST DILLON BAIER (B013001). * B013001 CREATED DATE :07/21/2021 CREATED TIME: 7:57:51 PM BROKEN FROG. BOLT. SEVERAL	2021/08/02	010764609 500000002

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100140878410001	0133A12 Loose, worn, missing frog bolts	1057.995				OTHER LOOSE .		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100140878420001	0133A14 Loose/worn/missing gr component	1057.995	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	07/21/2021 21:02:04 CST DILLON BAIER (B013001).* B013001 CREATED DATE :07/21/2021 CREATED TIME: 7:58:44 PM MISSING. HARDWARE ON GUARD RAIL. SECTION NEEDS TO ADJUST, BRING MORE HARDW.* ARE .	2021/08/02	010764609500000002

Total Record count: 252

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100140878430001	0133A14 Loose/worn/missing gr component	1057.995	GUARD RAIL MATERIAL	.00	No add'l action/Trk OK for posted speed	07/21/2021 21:02:07 CST DILLON BAIER (B013001).* B013001 CREATED DATE :07/21/2021 CREATED TIME: 7:59:10 PM MISSING. HARDWARE ON GUARD RAIL. SECTION NEEDS TO ADJUST, BRING MORE HARDW.* ARE .	2021/08/02	01076460950000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/08/02	01076444760000002
Inspection Date :2021/08/04																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/08/04	01076460950000008
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/08/04	01076444760000003
Inspection Date :2021/08/09																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/08/09	01086530760000002

Total Record count: 257

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/09	010865511 600000002
Inspection Date :2021/08/12																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/12	010865307 600000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/12	010865511 600000004
Inspection Date :2021/08/16																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/16	010965927 900000003
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/16	010966015 900000002
Inspection Date :2021/08/19																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/19	010965927 900000016
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/19	010966015 900000006
Inspection Date :2021/08/23																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/23	011074557 100000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/23	011074683 000000002
Inspection Date :2021/08/27																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/27	011074557 100000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/27	011074683 000000004
Inspection Date :2021/08/30																		

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1014.745	1014.745	1014.745_TURN_#20_3598E_136LB_LP OWER			YES			JOHNSON, GREGORY								2021/08/30	010741507 400000002
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/30	011179154 800000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/08/30	011179065 200000002
Inspection Date :2021/09/02																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100145 2169800 01	0133A15 Fastening s not intact/maint ained	1064.691	SW PLATES	.00	No add'l action/Trk OK for posted speed	08/30/2021 23:46:55 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :08/30/2021 CREATED TIME: 8:40:22 PM ZERO PLATE ON. WEST DAP TIE IS BROKE UNDER NORTH RAIL. .	2021/09/02	011179154 800000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/02	011179065 200000004
Inspection Date :2021/09/03																		
0036	1011.975	1041.600	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/03	011179154 800000007

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
Inspection Date :2021/09/07																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY	0100145 2169800 01	0133A15 Fastening s not intact/maint ained	1064.691	SW PLATES	.00	No add'l action/Trk OK for posted speed	08/30/2021 23:46:55 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :08/30/2021 CREATED TIME: 8:40:22 PM ZERO PLATE ON. WEST DAP TIE IS BROKE UNDER NORTH RAIL. .	2021/09/07	011308786 800000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/07	011308155 800000002
Inspection Date :2021/09/10																		

Total Record count: 276

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1013.000	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY	0100145 2169800 01	0133A15 Fastenings not intact/maintained	1064.691	SW PLATES	.00	No add'l action/Trk OK for posted speed	08/30/2021 23:46:55 CST GREGORY JOHNSON (B005500). * B005500 CREATED DATE :08/30/2021 CREATED TIME: 8:40:22 PM ZERO PLATE ON. WEST DAP TIE IS BROKE UNDER NORTH RAIL. .	2021/09/10	011308786 800000006
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/09/10	011308155 800000003
Inspection Date :2021/09/14																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/09/14	011412981 100000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/09/14	011413198 300000002
Inspection Date :2021/09/16																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/WALK				JOHNSON, GREGORY								2021/09/16	011412981 100000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELOW	OBS	HYRAIL/WALK				JOHNSON, GREGORY								2021/09/16	011413198 300000003
Inspection Date :2021/09/21																		

FRA TRACK INSPECTION- EAM

Report Criteria: LSMP: Line Segment: 36 Mile Post Range: 1014 to 1015

Report Timeframe: 09/29/2020 TO 09/29/2021

Report Execution Date: 09/29/2021

LS	BMP	EMP	Asset/ Track	Trav	By	Switch Thrown	Special Insp	Joint Insp	Inspected by	Defect Number	FRA Defect Code	Defect BMP	Meas Desc	Meas Amt	Remedial Action	Defect Comments	Uploaded Timestamp	Insp Number
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL				JOHNSON, GREGORY	0100146 9407200 01	0133A9 Loose, worn, missing adj braces	1024.794	RAIL BRACES	.00	Defect repaired since last inspection		2021/09/21	011527479 500000002
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/21	011527943 200000002
Inspection Date :2021/09/23																		
0036	1011.975	1065.362	MAIN_0	TVS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/23	011527479 500000004
0036	1014.745	1016.698	SDNG_10 14.745_35 98_BUELO W	OBS	HYRAIL/ WALK				JOHNSON, GREGORY								2021/09/23	011527943 200000003
Inspection Date :2021/09/28																		
0036	1011.975	1020.000	MAIN_0	TVS	HYRAIL/ WALK				ERIKSON, DAVID								2021/09/28	011635230 700000013

Total Record count: 286