

**UGI UTILITIES RESPONSE TO NTSB INFORMATION REQUEST
June 6, 2023**

NTSB Request No. 106: List and summarize all previous PHMSA-reportable incidents on UGI's assets involving Aldyl A and provide the PHMSA Report ID if known. The summary should include UGI's current understanding of the incident, even if it is different than what was most recently reported to PHMSA. At a minimum, include the date, city, state, location of failure (specific asset that failed), and cause. For each incident that involved an Aldyl A service tee, provide the report documenting UGI's failure investigation.

UGI Response:

The table below lists all reportable incidents that have been positively identified by UGI that reference Aldyl-A material. UGI will notify the NTSB if additional incidents containing Aldyl-A material are identified.

UGI reviewed its PHMSA DOT Distribution Incident Report data going back to the beginning of PHMSA record keeping (1970) and has concluded that there have been zero (0) incidents where a failure of Aldyl-A material was deemed to be the cause of the incident.

UGI PHMSA Reportable Incidents Containing Aldyl A							
District Office	PHMSA Report #	Date	Time	Address	City	Aldyl-A Component	Cause
Lancaster	20170064	7/2/2017	13:52	206 Springdale Lane	Millersville, PA	2" Aldyl A Main	Mechanical Perfection Service Tee failure.
Lancaster	20060162	9/2/2006	7:59	39 Apple Blossom Drive	West Lampeter, PA	2" Aldyl A Main	Mechanical Perfection Service Tee failure.
Reading	19990078	3/8/1999	8:05	213 S. 3rd Ave	West Reading, PA	2" Aldyl A Main	3rd Party Damage.
Archbald	19950017	8/31/1994	15:07	Oakford & Sturbridge Streets	Clarks Summit, PA	4" Aldyl A Main	Incorrect Operation, Construction Crew purging new 4" main into service when gas ignited.
Archbald	19900127	6/21/1990	15:38	28287 N. Main Avenue	Scranton, PA	6" Aldyl A Main	3rd Party Damage.
SouthPoint	1840711	5/11/1984	13:30	Seibert Hall - Susquehanna University	Selinsgrove, PA	4" Aldyl A Service Line	3rd Party Damage.