



**VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT
ATTACHMENT**

Vehicle Photographs

Pala Mesa, California

HWY20FH003

(3 Photographs)



View of the damage to Freightliner bus as photographed from left front corner.



View of damage to the Freightliner bus as photographed from the right front corner.



Photo shows the tread wear to the left rear outside dual tire.