



Photo 1 – Damage to cross tubes in tail boom