

Zoë Keliher  
Senior Aircraft Accident Investigator  
Western Pacific Region

**Subject:** WPR21FA265

Kamron Blevins - North Wing Inc.,

Mr. Blevins stated that the builder had used nylock nuts rather than spin nuts and keeper pins. He stated that was ok if he did not what to take the wing down easily. I would think that would be the front tube of the trike. I have not seen a upper trike mast like that. Must be a home built.

He put the bolt in the wrong way on the Base tube, should be horizontal.

Jennifer Kizer - Pilot's Spouse 03/31/2022

Ms. Kizer stated that following the accident, the family did a teardown of the engine. They found no mechanical malfunctions or anomalies with the engine.

Deputy Alex Wilson - Responding Law Enforcement

Deputy Wilson stated that the wind was gusting and strong following the accident.