

On Scene Photos
Courtesy of the Federal Aviation Administration



Figure 1: Left side of Airplane



Figure 2: Left Horizontal Stabilizer

On Scene Photos
Courtesy of the Federal Aviation Administration



Figure 3: Right side of Airplane



Figure 4: Outboard Right Wing

On Scene Photos
Courtesy of the Federal Aviation Administration



Figure 5: Right-Wing leading edge crush Damage

END.

Submitted by: Samantha Link