



Photo 1 – Photo of the damage to the airplane. Courtesy of the owner.



Photo 2 – View of the left rudder cable thimble. Courtesy of the owner.



Photo 3 - View of the control cable and nicopress swage. Courtesy of the owner.



Photo 4 - View of the control cable and nicopress swage. Courtesy of the owner.