

CEN23LA387

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damaged Right Wing Leading Edge (Courtesy of FAA)



Photograph 2 - Damaged Right Wing Leading Edge (Courtesy of FAA)