

ANC24LA035

**INVESTIGATION PHOTOGRAPHS**



**Photograph 1 - Image of wings, fuselage, and empennage (Courtesy of Airport Manager)**




**Photograph 2 - Image of left wing, fuselage, and empennage (Courtesy of Airport Manager)**





**Photograph 3 - Image of tire signature on runway surface (Courtesy of Airport Manager)**



**Photograph 4 - Image of tire signatures on taxiway surface (Courtesy of Airport Manager)**