

WPR22FA331

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the forward fuselage, right wing, and engine. (Courtesy of the FAA)



Photograph 2 - View of the accident site. (Courtesy of the FAA)



Photograph 3 - View of the aft fuselage structure and oil coolers.



Photograph 4 - View of the recovered engine.