



**Highway Factors Photographs 1 through 6**

**Decatur, TN**

**HWY21FH001**

(4 pages)



Highway Factors Photo 1 – View of SR-58 looking to the north standing on the solid white line separating the northbound lane from the paved shoulder (Source: TDOT)



Highway Factors Photo 2 – View of SR-58 looking to the north standing on the solid double yellow lines separating the northbound lane from the southbound lane (Source: TDOT)



Highway Factors Photo 3 – View of SR-58 looking to the north standing in the northbound lane with the accident school bus located in the background. The orange dash lines denote the approximate location of the tire marks of the service truck (Source: THP)



Highway Factors Photo 4 – Another view of SR-58 looking to the north standing in the northbound lane with the accident school bus located in the background. The orange dash lines denote the approximate location of the tire marks of the service truck (Source: THP)





Highway Factors Photo 5 – Another view of SR-58 looking to the north standing in the northbound lane with the accident school bus located in the background. The orange dash lines denote the approximate location of the tire marks of the service truck (Source: THP)



Highway Factors Photo 6 – Another view of SR-58 looking to the north standing in the northbound lane with the accident school bus and service truck located in the background. The orange dash lines denote the approximate location of the tire marks of the service truck (Source: THP)