

HWY24FH004

FACTUAL REPORT OF INVESTIGATION

Group Chair's Factual Report - Attachment

Bus 5 Work Order 3-4-2024

(3 pages)

BUS DRIVERS REPAIR REQUEST

Receiving (Initial) AW
Date 3/1/24

DATE: 3/1/24

BUS NUMBER: 5

BUS DRIVER NAME (PLEASE PRINT): J. FF

LOCATION	COMPONENT	DEFECT OR PROBLEM (Detailed description)
<i>Example: Exterior-Roof EX. RO</i>	Front Roof Hatch	Leaking when raining and won't latch tight
1. <i>Lube EX</i>	<i>UNS REFR LS RS</i>	<i>Lube Due 59000</i>
2.		
3.		
4.		
5.		
6.		

EXTERIOR CODES

EXTERIOR: EX
LEFT SIDE: LS
RIGHT SIDE: RS
FRONT: FR
REAR: RE
ROOF: RO
UNDERSIDE: UNS

INTERIOR

INTERIOR: IN
LEFT SIDE: LS
RIGHT SIDE: RS
FRONT: FR
REAR: RE
CEILING: CEIL
FLOOR: FL

ENGINE SHUTDOWN General Information:

Allow the engine to idle 3 to 5 minutes before shutting it off after a full-load operation. This allows adequate cool down of pistons, cylinders, bearings and turbocharger components.