



Airworthiness - Photo 4. Close-up view of the outboard portion of the right wing (view from forward looking aft). Note aftward accordion crush damage of the leading edge skin. (NTSB-C13)