



Airworthiness - Photo 5. View of the inboard section of the right wing (view from aft looking forward). Note damage to main spar (background). Also note entire left flap (foreground) and lack of bulging or bowing