



Airworthiness - Photo 6. View off the inboard section of the right wing (view from forward looking aft). Note damage to main spar and the 90-degree forward bend (foreground) (NTSB-C14)