



Airworthiness - Photo 7. Close-up view of the right wing spar area near 90-degree forward bend. Right main landing gear trunion (shown in foreground) is normally installed in this area. Note damage to the spar web in this area. (NTSB-I22)