



Airworthiness - Photo 10. View of inboard section of left wing spar. Note spar web damage and the diverging spar caps. Right main landing gear is normally stowed directly behind this area. (NTSB-16)