



Airworthiness - Photo 14. View of stabilator damage and upper structure of mating tail cone (denoted by arrow). Note bowing deformation of the tail cone and the rudder adjacent to it, and impact damage of the left stabilator. (NTSB-B10)