



Airworthiness - Photo 23. View of propeller assembly, prior to disassembly by investigators. Note "S" bending, chordwise scratching, and leading edge gouging. (NTSB-BB)