



Airworthiness - Photo 26. Overall view of engine prior to disassembly and inspection. Note that propeller had separated from the engine. Also note damage to the top of the no. 2 cylinder head section. (NTSB-AA)