



Airworthiness - Photo 28. Close-up view of the top of the no. 1 cylinder head section (view looking inboard) with propeller blade no. 1 resting next to it. Note consistent locations of blade damage with the cylinder damage. (NTSB-AA)