



# **Aviation Investigation Factual Report**

**Location:** Clark Fork, Idaho **Accident Number:** SEA06LA077

Date & Time: April 17, 2006, 14:30 Local Registration: N2288D

Aircraft Damage: Substantial

**Defining Event:** 1 Serious

Flight Conducted Under: Part 91: General aviation - Personal

#### **Factual Information**

On April 17, 2006, at 1400 Pacific daylight time, a Cessna 170B, N2288D, registered to and operated by the pilot as a 14 CFR Part 91 personal flight, collided with the terrain during an attempted go-around at River Lake Airstrip, Clark Fork, Idaho. Visual meteorological conditions prevailed at the time and a visual flight rules flight plan was filed. The aircraft was substantially damaged and the student pilot, the sole occupant, was seriously injured. The flight departed from Bonners Ferry, Idaho, about 30 minutes prior to the accident.

Due to the pilot's injuries, he does not recall the landing event, however, witnesses in the area reported that the aircraft was landing on runway 14 with a quartering tailwind. The witnesses observed the aircraft "tipping from one wheel to the other," and "bouncing back and forth on its wheels and swerving." The aircraft then lifted off and "flew across the road, rocking side to side then from 30 feet went nose down by the tracks in a ditch."

The aircraft came to rest nose down to the ground about 430 feet from the end of runway 14.

The nearest weather reporting facility located 19 nautical miles northwest of the accident site was reporting a wind from 260 degrees at 14 knots, gusting to 18 knots.

#### **Pilot Information**

Certificate:	Student	Age:	58,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3	Last FAA Medical Exam:	March 1, 2006
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	95 hours (Total, this make and mod	el)	

Page 2 of 5 SEA06LA077

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N2288D
Model/Series:	170B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20440
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	April 1, 2006 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	2 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3865 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-300
Registered Owner:	Lavern R. Harris	Rated Power:	145 Horsepower
Operator:		Operating Certificate(s) Held:	None

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SZT,2131 ft msl	Distance from Accident Site:	19 Nautical Miles
Observation Time:	14:07 Local	Direction from Accident Site:	285°
<b>Lowest Cloud Condition:</b>	Few / 7000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	14 knots / 18 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	11°C / -3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Bonners Ferry, ID (65S)	Type of Flight Plan Filed:	None
Destination:	(ID75)	Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	

Page 3 of 5 SEA06LA077

## **Airport Information**

Airport:	River Lake	Runway Surface Type:	Grass/turf
Airport Elevation:	2070 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	2600 ft / 60 ft	VFR Approach/Landing:	Traffic pattern

### Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	48.116664,-116.166664

Page 4 of 5 SEA06LA077

#### **Administrative Information**

Investigator In Charge (IIC):	Eckrote, Debra	
Additional Participating Persons:	John H Phillips; FAA/FSDO; Spokane, WA	
Report Date:	June 1, 2006	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=63525	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA06LA077