



Aviation Investigation Final Report

Location: Kotzebue, Alaska Accident Number: ANC20CA088

Date & Time: August 21, 2020, 19:00 Local Registration: N9128T

Aircraft Damage: Substantial

Defining Event: Loss of control in flight **Injuries:** 2 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

Analysis

The pilot reported that during the downhill takeoff from a remote unimproved airstrip, with a quartering headwind, the wind shifted as the airplane became airborne. The airplane settled "with about 100 yds left on the runway" and he continued "trying to milk the flaps" to become airborne while continuing downhill. The airplane never attained flying speed again and settled into a creek bed. After the impact with terrain, the pilot reported there were "several wind gusts of 15-20 mph coming downhill".

The airplane sustained substantial damage to the fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain an airspeed conducive to flight during takeoff.

Findings

Aircraft Airspeed - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Gusts - Effect on operation

Page 2 of 6 ANC20CA088

Factual Information

History of Flight

Takeoff	Other weather encounter
Takeoff	Loss of control in flight (Defining event)
Takeoff	Attempted remediation/recovery
Takeoff	Runway excursion
Takeoff	Nose over/nose down

Pilot Information

Certificate:	Commercial; Private	Age:	72,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	April 2, 2020
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	July 12, 2020
Flight Time:	(Estimated) 40000 hours (Total, all aircraft), 10000 hours (Total, this make and model), 40000 hours (Pilot In Command, all aircraft)		

Page 3 of 6 ANC20CA088

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9128T
Model/Series:	180 B	Aircraft Category:	Airplane
Year of Manufacture:	1959	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	50628
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-470 SERIES
Registered Owner:	On file	Rated Power:	255 Horsepower
Operator:	On file	Operating Certificate(s) Held:	On-demand air taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAFM,289 ft msl	Distance from Accident Site:	75 Nautical Miles
Observation Time:	04:56 Local	Direction from Accident Site:	173°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.79 inches Hg	Temperature/Dew Point:	21°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Kotzebue, AK (OTZ)	Type of Flight Plan Filed:	None
Destination:	Kotzebue, AK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 4 of 6 ANC20CA088

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	68.330558,-158.2411(est)

Page 5 of 6 ANC20CA088

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Scot Brown; FAA; Fairbanks, AK
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class 4
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=101901

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.

Page 6 of 6 ANC20CA088