



Aviation Investigation Final Report

Location: KENTLAND, Indiana Accident Number: CHI83LA293

Date & Time: July 3, 1983, 13:30 Local Registration: N4558E

Aircraft: GRUMMAN AA-5B Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING ARRIVAL, THE PLT LANDED ON RWY 27 WITH A LEFT X-WIND FROM THE SOUTH. HE STATED THAT HE HAD NO INDICATION OF EXCESSIVE X-WINDS OR GUSTS UNTIL THE ACFT WAS ABOUT TO TOUCH DOWN. HE STATED THAT AT THAT TIME, THE PLANE ENCOUNTERED HEAVY GUSTS & A DOWNDRAFT. SUBSEQUENTLY, THE ACFT LANDED HARD & THE NOSE GEAR COLLAPSED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - GUSTS

3. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

Occurrence #2: NOSE GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. (F) LANDING GEAR, NOSE GEAR - OVERLOAD

Page 2 of 5 CHI83LA293

Factual Information

Pilot Information

Certificate:	Commercial	Age:	65,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 23, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2550 hours (Total, all aircraft), 50 hours (Total, this make and model), 2374 hours (Pilot In Command, all aircraft), 78 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	GRUMMAN	Registration:	N4558E
Model/Series:	AA-5B AA-5B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1239
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 7, 1983 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	45 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	240 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated	Engine Model/Series:	0-320-A4K
Registered Owner:	MAURICE H. DOWLING	Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 CHI83LA293

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dawn
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	25 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	31°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ROCKFORD , IL (RED)	Type of Flight Plan Filed:	None
Destination:	KENTLAND , IN (50I)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	KENTLAND 50I	Runway Surface Type:	Asphalt
Airport Elevation:	698 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3500 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Page 4 of 5 CHI83LA293

Administrative Information

Investigator In Charge (IIC):	Seidlein, George
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=12244

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CHI83LA293