

Aviation Investigation Final Report

Location:	EVELETH, Minnesota	3	Accident Number:	CHI84LA069
Date & Time:	December 29, 1983,	13:00 Local	Registration:	N9611G
Aircraft:	CESSNA	U206F	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

THE PLT REPORTED THAT AFTER TAKING OFF, THE CABIN BEGAN TO FILL WITH SMOKE. HE RETURNED TO THE ARPT FOR A PRECAUTIONARY LANDING; HOWEVER, DURING TOUCHDOWN, THE LEFT WING COLLIDED WITH A SNOWBANK BESIDE THE RWY. AN EXAM OF THE ACFT REVEALED THAT WITH THE ENG SHUT DOWN, NO SMOKE WOULD DEVELOPE WHEN THE MASTER SWITCH WAS TURNED ON. HOWEVER, AFTER THE ENG WAS STARTED, SMOKE APPEARED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (F) ELECTRICAL SYSTEM - UNDETERMINED 2. (F) ELECTRICAL SYSTEM - OVERTEMPERATURE

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

- Findings 3. (F) TERRAIN CONDITION SNOWBANK 4. (C) CLEARANCE MISJUDGED PILOT IN COMMAND 5. (C) DIVERTED ATTENTION PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	41,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical–no waivers/lim.	Last FAA Medical Exam:	May 5, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	399 hours (Total, all aircraft), 399 hours (Total, this make and model), 358 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N9611G
Model/Series:	U206F U206F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	U20601811
Landing Gear Type:	Retractable - Tailwheel	Seats:	б
Date/Type of Last Inspection:	May 20, 1983 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	855 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-F
Registered Owner:	LOUIS J. AHACHICH	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots / 10 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:	GRAND RAPIDS , MN	Type of Clearance:	None
Departure Time:	12:55 Local	Type of Airspace:	Class G

Airport Information

Airport:	ELY LAKE	Runway Surface Type:	Grass/turf
Airport Elevation:	1375 ft msl	Runway Surface Condition:	Snow
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1800 ft	VFR Approach/Landing:	Precautionary landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	47.459224,-92.540336(est)

Administrative Information

Investigator In Charge (IIC):	Kleckner, Pamela
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=12512

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.