



Aviation Investigation Final Report

Location: MOUNT GILEAD, Ohio Accident Number: CHI86LA061

Date & Time: January 11, 1986, 13:00 Local Registration: N3003Z

Aircraft: PIPER PA-22-150 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

ACCORDING TO THE ARPT MANAGER, THE PLT WAS TAXIING DOWN THE ACTIVE IN GUSTY WIND CONDITIONS AT A FAIRLY RAPID RATE OF SPEED. AS THE PLT TURNED INTO THE RUN-UP PAD AREA THE ACFT NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE OVER

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (C) COMPENSATION FOR WIND CONDITIONS - POOR - PILOT IN COMMAND

2. (C) AIRCRAFT HANDLING - IMPROPER - PILOT IN COMMAND

3. (C) FLT CONTROL SYST, ELEVATOR CONTROL - IMPROPER

4. (C) FLT CONTROL SYST, AILERON CONTROL - IMPROPER

Factual Information

Pilot Information

Certificate:	Private	Age:	39,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 18, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	288 hours (Total, all aircraft), 40 hours (Total, this make and model), 250 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N3003Z
Model/Series:	PA-22-150 PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	226954
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	July 14, 1985 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3031 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-320-B2B
Registered Owner:	KEVIN R. COCHRAN	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 CHI86LA061

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MFD ,1296 ft msl	Distance from Accident Site:	22 Nautical Miles
Observation Time:	12:50 Local	Direction from Accident Site:	30°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	14 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	3°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	MOUNT GILEAD , OH (419M)	Type of Flight Plan Filed:	None
Destination:	COLUMBUS , OH (PVT)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	MORROW COUNTY 419	Runway Surface Type:	Asphalt
Airport Elevation:	1080 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3500 ft / 65 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	40.490566,-82.890869(est)

Page 3 of 4 CHI86LA061

Administrative Information

Investigator In Charge (IIC):	Mcavoy, E.	
Additional Participating Persons:	H BURKES; COLUMBUS , OH	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=13403	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CHI86LA061