

Aviation Investigation Final Report

Location:	CRESTWOOD, Illing	pis	Accident Number:	CHI87DEE02
Date & Time:	October 9, 1986, 04	4:20 Local	Registration:	N6955Y
Aircraft:	PIPER	PA-23-250	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	viation		

Analysis

THE AIRCRAFT WAS FLOWN WITHOUT AUTHORIZATION FROM THE OWNER BY UNKNOWN PERSON(S). UPON LANDING, DIRECTIONAL CONTROL WAS LOST. THE AIRCRAFT SKIDDED OFF THE RUNWAY INTO AN AIRCRAFT TIE-DOWN AREA AND COLLIDED WITH A PARKED AIRCRAFT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND 2. (C) GROUND LOOP/SWERVE - UNCONTROLLED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Findings 3. OBJECT - AIRCRAFT PARKED/STANDING

Factual Information

Pilot Information

Certificate:		Age:	U
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

PIPER	Registration:	N6955Y
PA-23-250 PA-23-250	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	274320
Retractable - Tricycle	Seats:	6
August 9, 1985 Annual	Certified Max Gross Wt.:	5200 lbs
14 Hrs	Engines:	2 Reciprocating
835 Hrs	Engine Manufacturer:	LYCOMING
Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-540-C4B5
VEE-JAY PRODUCTS, INC.	Rated Power:	250 Horsepower
	Operating Certificate(s) Held:	None
	Operator Designator Code:	
	PA-23-250 PA-23-250 Normal Retractable - Tricycle August 9, 1985 Annual 14 Hrs 835 Hrs Installed, activated, did not aid in locating accident	PA-23-250 PA-23-250Aircraft Category: Amateur Built:NormalSerial Number:NormalSerial Number:Retractable - TricycleSeats:August 9, 1985 AnnualCertified Max Gross Wt.:14 HrsEngines:835 HrsEngine Manufacturer:Installed, activated, did not aid in locating accidentRated Power:VEE-JAY PRODUCTS, INC.Rated Power:Operating Certificate(s) eld:Serial Certificate(s)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/dark
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	HOWELL 3HW	Runway Surface Type:	Asphalt
Airport Elevation:	600 ft msl	Runway Surface Condition:	
Runway Used:	13	IFR Approach:	None
Runway Length/Width:	3500 ft / 40 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	41.619388,-87.719345(est)

Administrative Information

Investigator In Charge (IIC):	Bell, Thomas	
Additional Participating Persons:	JOHN TOY;	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=13551	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.