



Aviation Investigation Final Report

Location: HIBBING, Minnesota Accident Number: CHI87LA105

Date & Time: March 28, 1987, 09:50 Local Registration: N1156H

Aircraft: AERONCA 15AC Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT STATED THAT WHILE TAXIING ON THE NORTH TAXIWAY, FOR TAKEOFF ON RUNWAY 31, A 'GUST OF WIND CAUGHT THE TAIL ABRUPTLY AND CAUSED PLANE TO VEER TO THE LEFT AND STRIKE CORNER OF HANGAR.' THE ACFT COLLIDED WITH THE HANGAR NOSE FIRST.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. WEATHER CONDITION - CROSSWIND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - TO TAKEOFF

Findings
3. OBJECT - AIRPORT FACILITY

Page 2 of 5 CHI87LA105

Factual Information

Pilot Information

Certificate:	Private	Age:	60,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	March 17, 1987
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3100 hours (Total, all aircraft), 140 hours (Total, this make and model), 4 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	AERONCA	Registration:	N1156H
Model/Series:	15AC 15AC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	15AC166
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	April 13, 1986 Annual	Certified Max Gross Wt.:	2050 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3102 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated	Engine Model/Series:	0-360
Registered Owner:	SWAN LAKE FLYERS	Rated Power:	180 Horsepower
Operator:	SWAN LAKE FLYERS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 CHI87LA105

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HIB ,1352 ft msl	Distance from Accident Site:	
Observation Time:	09:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	18 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-9°C / -17°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	VFR
Destination:	CLEAR LAKE , MN (8Y6)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	CHISHOLMHIBBING H1B	Runway Surface Type:	Asphalt
Airport Elevation:	1352 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.400939,-92.940727(est)

Page 4 of 5 CHI87LA105

Administrative Information

Investigator In Charge (IIC):	Carmien, A
Additional Participating Persons:	
Original Publish Date:	March 30, 1988
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=13749

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CHI87LA105