

Aviation Investigation Final Report

Location:	QUINCY, Illinois		Accident Number:	CHI89LA006
Date & Time:	October 9, 1988, 16	:20 Local	Registration:	N8769R
Aircraft:	BEECH	55B	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation			

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT IN COMMAND'S FAILURE TO MAINTAIN CONTROL OF THE AIRCRAFT AND TO TAKE APPROPRIATE ACTION TO CORRECT THE PORPOISE.

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #2: NOSE GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Private	Age:	54.Male
Gertificate.	1 mate	Aye.	J-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	September 22, 1987
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	890 hours (Total, all aircraft), 199 hours (Total, this make and model), 725 hours (Pilot In Command, all aircraft), 15 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N8769R
Model/Series:	55B 55B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	TC1790
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	February 3, 1988 Annual	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:	45 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	2090 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-470L
Registered Owner:	DELMARVA ENGINEERING ASSOC LTD	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	UIN ,769 ft msl	Distance from Accident Site:	
Observation Time:	16:50 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4500 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	17°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	BUFFALO , NY (BUF)	Type of Flight Plan Filed:	None
Destination:	KANSAS CITY , KS (OJC)	Type of Clearance:	None
Departure Time:	13:55 Local	Type of Airspace:	Class G

Airport Information

Airport:	QUINCY-BALDWIN FLD UIN	Runway Surface Type:	Asphalt
Airport Elevation:	769 ft msl	Runway Surface Condition:	Dry
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	5400 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Dinwiddie, Carl	
Additional Participating Persons:	R. ATKINS; SPRINGFIELD , IL	
Original Publish Date:	July 9, 1990	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=14296	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.