



Aviation Investigation Final Report

Location: MASON, Michigan Accident Number: CHI91LA012

Date & Time: October 14, 1990, 11:00 Local Registration: N2600A

Aircraft: PIPER PA-22-135 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT REPORTED THAT HE WAS ATTEMPTING TO LAND IN WINDS GUSTING FROM 10 TO 20 KNOTS, WITH AN 80 DEGREE CROSSWIND COMPONENT. HE SAID THAT HE LOST DIRECTIONAL CONTROL, AND THAT THE AIRPLANE WEATHER VANED INTO THE WIND, CAUSING THE NOSE GEAR TO COLLAPSE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL. A FACTOR IN THE ACCIDENT IS THE PILOT'S LACK OF TOTAL EXPERIENCE IN THE ACCIDENT TYPE AIRPLANE.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. WEATHER CONDITION - CROSSWIND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT - PILOT IN COMMAND

Occurrence #2: NOSE GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Page 2 of 5 CHI91LA012

Factual Information

Pilot Information

Certificate:	Private	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 21, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	79 hours (Total, all aircraft), 2 hours (Total, this make and model), 29 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2600A
Model/Series:	PA-22-135 PA-22-135	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	882
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-290-D2
Registered Owner:		Rated Power:	135 Horsepower
Operator:	LOFTON, CHARLES W.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 CHI91LA012

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 10000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:48 Local	Type of Airspace:	

Airport Information

Airport:	MASON JEWETT 09G	Runway Surface Type:	Asphalt
Airport Elevation:	920 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3500 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.580818,-84.43972(est)

Page 4 of 5 CHI91LA012

Administrative Information

Investigator In Charge (IIC):

La belle, James

Additional Participating
Persons:

Original Publish Date:

November 9, 1992

Last Revision Date:

Investigation Class:

Class

Note:

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=14943

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CHI91LA012