



Aviation Investigation Final Report

Location:	OLATHE, Kansas	Accident Number:	CHI91LA200
Date & Time:	June 24, 1991, 14:40 Local	Registration:	N87113
Aircraft:	BELLANCA 8GCBC	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

THE PILOT SAID THAT WHILE PRACTICING TOUCH AND GO LANDINGS IN A LIGHT CROSSWIND, DIRECTIONAL CONTROL WAS LOST. THE AIRCRAFT VEERED OFF THE RUNWAY, HIT A RUNWAY LIGHT AND NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: DIRECTIONAL CONTROL WAS NOT MAINTAINED BY THE PILOT. A FACTOR RELATED TO THE ACCIDENT IS CROSSWIND.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND
2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Occurrence #3: NOSE OVER
Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Private	Age:	31, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	June 24, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	447 hours (Total, all aircraft), 15 hours (Total, this make and model), 50 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N87113
Model/Series:	8GCBC 8GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	69-74
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 2, 2000 Annual	Certified Max Gross Wt.:	2150 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	190 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-360-C2E
Registered Owner:		Rated Power:	180 Horsepower
Operator:	WADE V. ROBINETT	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	OJC ,1096 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	14:42 Local	Direction from Accident Site:	1°
Lowest Cloud Condition:	Unknown	Visibility	4 miles
Lowest Ceiling:	Broken / 2500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	100°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	Class D;Class E

Airport Information

Airport:	JOHNSON COUNTY EXECUTIVE OJC	Runway Surface Type:	Asphalt
Airport Elevation:	1096 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	4099 ft / 75 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.839126,-94.780426(est)

Administrative Information

Investigator In Charge (IIC): Hruban, John

Additional Participating Persons: BOB HANSEN;

Original Publish Date: March 24, 1993

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=15106>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).