



# **Aviation Investigation Final Report**

Location: CLINTON, Maryland Incident Number: DCA83IA027

Date & Time: June 2, 1983, 15:00 Local Registration: N9542L

Aircraft: GRUMMAN AA-5 Aircraft Damage: Minor

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

THE STUDENT PILOT BALLOONED DURING THE FLARE, THEN LANDED HARED ON RUNWAY. THE NOSEGEAR FAILED AND THE ACFT SLID DOWN THE RUNWAY.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

#### **Findings**

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

**Findings** 

1. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER USE OF - PILOT IN COMMAND

## **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	30 hours (Total, all aircraft), 30 hour	rs (Total, this make and model)	

### **Aircraft and Owner/Operator Information**

Aircraft Make:	GRUMMAN	Registration:	N9542L
Model/Series:	AA-5 AA-5	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3960104
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-320-E2G
Registered Owner:	TERRY D. STICE	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DCA83IA027

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class D

## **Airport Information**

Airport:	HYDE W32	Runway Surface Type:	Asphalt
Airport Elevation:	249 ft msl	Runway Surface Condition:	Dry
Runway Used:	31	IFR Approach:	
Runway Length/Width:	2000 ft / 40 ft	VFR Approach/Landing:	Touch and go

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Minor
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 3 of 4 DCA83IA027

#### **Administrative Information**

Investigator In Charge (IIC):	Schleede, Ronald
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=15792

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DCA83IA027